

Service Information Letter

TO : All EC135 P2+ Operators
FROM : FDC/aerofilter Engineering
EFFECTIVITY : All EC135 P2+ Helicopters modified IAW STC SR02059SE
REFERENCE : 1135-SERIES-INS-5, Revision B
DATE : December 09, 2010

TYPOGRAPHICAL ERRORS IN INSTALLATION INSTRUCTIONS

There are typographical errors on several pages of the Installation Instructions (1135-SERIES-INS-5, Revision B) provided with the FDC/aerofilter Inlet Barrier Filter Kit for the EC135 P2+. The typographical errors DO NOT appear on drawings 1135N5, Revision D (Installation, EC135 Filter System), and 1135E1, Revision C (Harness Assy, Main).

Please refer to the corrections below and note the changes:

All references to p/n 1135E5-1 should be 1135E5-3 in the following locations:

- Page 4 (Table of Contents)
- Page 53, Section 6.5 Title
- Page 53, Section 6.5.1(a)
- Page 54, Section 6.5.3(a)

All references to p/n 1135E5-2 should be 1135E5-4 in the following locations:

- Page 4 (Table of Contents)
- Page 53, Section 6.5 Title
- Page 53, Section 6.5.1(c)
- Page 54, Section 6.5.3(b)

All references to drawing 1135E5 should be 1135N5 in the following locations:

- Page 54, Section 6.5.3(c and d)

On page 57, section 7.1.4(d):

The reference to [ICA 7.3.3] should be [ICA 7.3.4].

On page 57, section 7.1.4(e):

The reference to [ICA 7.3.4] should be [ICA 7.3.5].

Service Information Letter

It is the intent of FDC/aerofilter engineering to make these corrections at the next document revision.

For FDC/aerofilter Engineering,



Don M. Nelson
Engineering Manager, FDC/aerofilter